

General Environmental Incident Summary

Incident: 3390 **Date/Time Notice:** 7/18/2014 12:45 **DEM Incident No:**

Responsible Party: Minnesota Power

Date Incident: 7/18/2014 **Time Incident:** 0900 **Duration:**

County: Morton **Twp:** 140 **Rng:** 85 **Sec:** 5 **Qtr:** NW

Lat: 46.97477 **Long:** -101.44550 **Method:** Interpolation from map

Location Description: North on Hwy 25 from the town of New Salem, Left(West) 31st st SW, West ¼ mile, north ¼, East ¼ mile

Submitted By: Greg Prom

Affiliation: Minnesota Power

Address: 30 West Superior Street

City: Duluth

State: MN

Zip: 55811

Received By:

Contact Person: Greg Prom
30 West Superior Street
Duluth, MN 55802

Distance Nearest Occupied Building: 5100 Feet

Release Contained: Yes

Type of Incident: hydraulic hose leak

Description of Released Contaminant: Hydraulic Oil

Volume Spilled: 10.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: No

Cause of Incident:

hydraulic line leak at Tower #3.

Risk Evaluation:

The spill has been contained and the leak has been fixed. The spill has been cleaned up. and there is no more risks at this time.

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

There was a minimal impact to surficial soil. Since the cleanup was performed promptly and the volume of the spill was relatively minimal the risk to surface water and groundwater is minimal to non-existent.

Action Taken or Planned:

Used a grader to remove soil and denatured alcohol to clean-up surface areas

Wastes Disposal Location: To be determined. Stored in dumpster at site.

Agencies Involved:

Updates

Date: 7/18/2014 ***Status:*** Reviewed - No Action Required

Author: Roberts, Kris

Updated Volume:

Notes:

A small volume spill of hydraulic oil. The response was fast with the removal of impacted materials. No on-site follow-up necessary.